

dgrimmer

From: Ernie.Sweet@erm.com
Sent: Wednesday, April 24, 2002 4:13 PM
To: dgrimmer@thebakercompanies.com
Subject: Laboratory Results for Furnace Dock facility location

Hi Doug,
 I will also be faxing hard copy of this e-mail and lab report to you asap.

----- Forwarded by Ernie Sweet/ERMNEST/ERM on 04/24/02 04:06 PM -----

Ernie Sweet

04/16/02 02:04 PM

To: dgrimmer@thebakercompanies.com
cc:
Subject: Laboratory Results for Furnace Dock facility location



Hi Doug,

The following information was obtained from the Galson Laboratories analytical report various building materials samples obtained during a visual survey of the Furnace Dock facility location that ERM conducted with you on 27 February, 2001.

Please note that ERM's visual survey was limited to accessible areas of the subject property and as a result ERM recommends that you should intend to utilize the services of an asbestos abatement contractor to remove asbestos containing building materials (ACBM) from that facility, that they conduct their own assessment of the facility to insure that they have identified all ACBM in the facility per NYS ICR 56 requirements.

Sample 1-FC -insulating material on large heat exchanger equipment located in Southwest corner- 65 % chrysotile asbestos

Sample 2-FC- green colored flooring material and mastic- flooring material does not contain asbestos, mastic has 45 % chrysotile asbestos

Sample 3-FC- pink colored floor tile material does not contain asbestos

Sample 4-FC- brown colored fiberboard ceiling material- does not contain asbestos

Sample 5-FC -piping systems insulation material- 25 % chrysotile asbestos

Sample 6-FC- insulating material on small round shaped metal piece of equipment does not contain asbestos

Sample 9-FC- piping systems insulation material residue on floor of facility - 25 % chrysotile asbestos

Sample 10-FC- Detached shed's asphalt roof material- does not contain asbestos

Sample 11-FC-Pink colored building mastic material on exterior of facility at Northeast end-greater than 1 % chrysotile asbestos

4/24/02

BCLP02757

Sample 12-FC-black colored mastic material on interior wall surface (north end of facility) greater than 1 % chrysotile asbestos

Sample 13-FC-Facility roof mastic building material- greater than 1 % chrysotile asbestos

Sample 14-FC-Facility roof mastic building material- greater than 1 % chrysotile asbestos

Sample 15-FC-Facility roof mastic building material- greater than 1 % chrysotile asbestos

Samples 7-FC and 8-FC were interior and exterior paint samples that are not classified by EPA as lead based paint materials however the paint s do contain 0.028 and 0.016 % lead respectively.

Galson Laboratories analytical report was faxed to you on 16 April, 2002.

**Environmental
Resources
Management**

5788 Widewaters Parkway
DeWitt, New York 13214
(315) 445-2554
(315) 445-2543 (fax)

Facsimile

From:

Ernie Sweet

To:

Dwy

Co:

the

Fax No.

914-747-9275

To:

Thommes

Co:

Baker

Fax No.

To:

Co:

Compass

Fax No.

Project/Proposal No.:

58309.001

Date:

Number of Pages:

9

(Including Cover Page)

Original:

☒

Will Follow

☐

Will Not Follow

VIA

☒


Mail

☐

Overnight Courier

☐

Hand Delivery

**ERM**

16 Amy
attached is e-mail and laboratory
report for Lawrence Park facility
Ernie

If you have any difficulty with this transmission, please call (315) 445-2554

PRIVILEGE AND CONFIDENTIALITY NOTICE

This message is intended only for the use of the individual(s) to who it is addressed and may contain information that is privileged and/or confidential. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering the message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately at (local phone number including area code) and return the original message to us at the address above via the U.S. Postal Service.
Thank you.

Ernie Sweet

04/16/02 02:04 PM

To: dgrimmer@thebakercompanies.com

cc:

Subject: Laboratory Results for Furnace Dock facility location



Hi Doug,

The following information was obtained from the Galson Laboratories analytical report various building materials samples obtained during a visual survey of the Furnace Dock facility location that ERM conducted with you on 27 February, 2001.

Please note that ERM's visual survey was limited to accessible areas of the subject property and as a result ERM recommends that you should intend to utilize the services of an asbestos abatement contractor to remove asbestos containing building materials (ACBM) from that facility, that they conduct their own assessment of the facility to insure that they have identified all ACBM in the facility per NYS ICR 56 requirements.

Sample 1-FC -insulating material on large heat exchanger equipment located in Southwest corner- 65 % chrysotile asbestos

Sample 2-FC- green colored flooring material and mastic- flooring material does not contain asbestos, mastic has 45 % chrysotile asbestos

Sample 3-FC- pink colored floor tile material does not contain asbestos

Sample 4-FC- brown colored fiberboard ceiling material- does not contain asbestos

Sample 5-FC -piping systems insulation material- 25 % chrysotile asbestos

Sample 6-FC- insulating material on small round shaped metal piece of equipment does not contain asbestos

Sample 9-FC- piping systems insulation material residue on floor of facility - 25 % chrysotile asbestos

Sample 10-FC- Detached shed's asphalt roof material- does not contain asbestos

Sample 11-FC-Pink colored building mastic material on exterior of facility at Northeast end-greater than 1 % chrysotile asbestos

Sample 12-FC-black colored mastic material on interior wall surface (north end of facility) greater than 1 % chrysotile asbestos

Sample 13-FC-Facility roof mastic building material- greater than 1 % chrysotile asbestos

Sample 14-FC-Facility roof mastic building material- greater than 1 % chrysotile asbestos

Sample 15-FC-Facility roof mastic building material- greater than 1 % chrysotile asbestos

Samples 7-FC and 8-FC were interior and exterior paint samples that are not classified by EPA as lead based paint materials however the paint s do contain 0.028 and 0.016 % lead respectively.

Galson Laboratories analytical report was faxed to you on 16 April, 2002.



6601 Kirkville Road
E. Syracuse, NY 13057-0369
Phone: (315) 432-5227
Fax: (315) 437-0571
www.galsonlabs.com

March 07, 2002

DOH ELAP# 11626

Mr. Ernie Sweet
ERM Inc.
5788 Widewaters Pwky.
Dewitt, NY 13214

Client Account# 11282

Login# L79409

Dear Mr. Sweet:

Enclosed are the analytical results of the samples received by our laboratory February 28, 2002.

Results in this report are based on the sampling data provided by the client. Unless otherwise requested, all samples will be discarded thirty days from the date of this report.

Please contact your client service representative, Nancy Ackerman at (888) 577-5227, extension 305, if you would like any additional information regarding this report.

Thank you for using Galson Laboratories.

Sincerely,

Galson Laboratories

F. Joseph Unangst
Laboratory Director

Enclosure(s)





LABORATORY ANALYSIS REPORT

6601 Kirkville Road
E. Syracuse, NY 13057-0369
Phone: (315) 432-5227
Fax: (315) 437-0571
www.galsonlabs.com

Client : ERM Inc.
Site : Furnac Creek
Project No. : 58810.01.01

Date Sampled : 28-FEB-02
Date Received : 28-FEB-02
Date Analyzed : 04-MAR-02

Account No.: 11282
Login No. : L79409

Bulk Asbestos Analysis

Sample ID	Lab ID	Color	%Asb.	Type 1	%Asb.	Type 2	%Asb.	Type 3	%/Type Other Fibers
1-FC	1	Gray/Beige	65	CH	ND	NA	ND	NA	ND
2-FC	2(L1)	Wt/Green	ND	NA	ND	NA	ND	NA	TR CE
2-FC	2(L2)	Tan	45	CH	ND	NA	ND	NA	10 CE,FG
* 3-FC	3	Orange	ND	NA	ND	NA	ND	NA	TR CE
4-FC	4	Brown	ND	NA	ND	NA	ND	NA	95 CE
5-FC	5	Gray	25	CH	ND	NA	ND	NA	50 CE
6-FC	6	Gray/Brown	ND	NA	ND	NA	ND	NA	70 FG
9-FC	9	Off White	35	CH	ND	NA	ND	NA	55 CE
* 10-FC	10	Gray/Black	ND	NA	ND	NA	ND	NA	35 CE,SY
* 11-FC	11	Gray/Black	>1	CH	ND	NA	ND	NA	1-5 CE
* 12-FC	12	Black	>1	CH	ND	NA	ND	NA	1-5 CE
13-FC	13(L1)	Brown/Blk	ND	NA	ND	NA	ND	NA	95 CE
13-FC	13(L2)	Black	>1	CH	ND	NA	ND	NA	TR CE
* 14-FC	14	Black/Brn	>1	CH	ND	NA	ND	NA	ND
* 15-FC	15	Black/Gray	>1	CH	ND	NA	ND	NA	10 CE

COMMENTS: Wt-White Blk-Black Brn-Brown

*NOB sample.

Field sampling was not performed by GALSON Laboratories.

Results are based on the sampling data provided by the client.

This report should not be reproduced except in full without the written approval of Galson Laboratories.

Analytical Method : Polarized light microscopy/
dispersion staining.
EPA 40 CFR Ch. 1 (7-1-87 Ed.)
Part 763, Subpart F, App. A.

Submitted by : MS/PW

Approved by : MS

Date : 06-MAR-02 QC by: *JS*

NYSDOH # : 11626

TR- Trace(< 1%)

CE- Cellulose

FG- Fibrous Glass

SY- Synthetic

AC- Actinolite

AM- Amosite

AN- Anthophyllite

CH- Chrysotile

CR- Crocidolite

TM- Tremolite

NA- Not Applicable

NS- Not Specified

ND- Not Detected

> - Greater than

Results relate only to items analyzed, and may not be used to claim product endorsement by NVLAP or any US government agency. Laboratory accredited under NYS ELAP(#11626) and NVLAP(#101375-0). Measurement uncertainty records based on interlab analysis are on file, and are available upon request.



**Galson
Laboratories**ASBESTOS COMMENTS

6601 Kirkville Road
E. Syracuse, NY 13057-0369
Phone: (315) 432-5227
Fax: (315) 437-0571
www.galsonlabs.com

Login # : L79409
Project : 58810.01.01

LAB ID	SAMPLE ID	SAMPLE/LAYER DESCRIPTION	% OF LAYER IN SAMPLE
2 (L1)	2-FC	Linoleum	50
2 (L2)	2-FC	Tile backing	50
13 (L1)	13-FC	Fibrous layer	80
13 (L2)	13-FC	Tar	20





LABORATORY ANALYSIS REPORT

6601 Kirkville Road
E. Syracuse, NY 13057-0369
Phone: (315) 432-5227
Fax: (315) 437-0571
www.galsonlabs.com

Client : ERM Inc.
Site : Furnac Creek
Project No. : 58810.01.01

Date Sampled : 28-FEB-02
Date Received : 28-FEB-02
Date Analyzed : 06-MAR-02

Account No.: 11282
Login No. : L79409

Lead

<u>Sample ID</u>	<u>Lab ID</u>	<u>Total mg/kg</u>	<u>Percent %</u>
7-FC	L79409-7	280	0.028
8-FC	L79409-8	160	0.016

Level of quantitation: 25 mg/kg

Analytical Method : EPA Pb 92-114172 Mod; ICP

OSHA PEL (TWA) : NA

Collection Media : Paint

Submitted by: KB

Approved by : AMW

Date : 07-MAR-02

QC by:

NYS DOH # : 11626

< -Less Than	mg -Milligrams	m3 -Cubic Meters	kg -Kilograms
> -Greater Than	ug -Micrograms	l -Liters	NS -Not Specified
NA -Not Applicable	ND -Not Detected	ppm -Parts per Million	



**Galsion**

Laboratories

6601 Kirkville Road

P.O. Box 369

E. Syracuse, NY 13057

Tel: (315) 437-7252 888-577-Labs (5227)

Fax: (315) 437-0571

Request For Industrial Hygiene AnalysisCompany Name: ERMSite Name: Pleasantville & furnace creekSampled By: ERMProject #: S8860-01.01Send Report to: Ernie SweetInvoice to: sameERM, Inc.5798 Henderson PkwySaratoga, NY 13214☐ Purchase order number _____

(or)

☐ Credit Card (type) _____☒ Verbal Authorization _____

Card # _____

Exp Date _____

☒ Standard Turn-Around Time

OR

☐ Rush: Date and Time Requested: _____

am

☐ Phone Results to: _____

Phone # () - -

ext.

☒ Fax Results to: 315-445-2543

Fax # () - -

☐ Email Results to: _____

Sample Identification	Date Sampled	Sample Medium Catalog # / Lot #	Air Sample Volume (liters)*	Analysis Requested	Method Reference
8-BP	2/27/02	X	X	full asbestos	Phm
9-BP					
10-BP					
11-BP					
12-BP					
1-FC	2/28/02				
2-FC					
3-FC					
4-FC					
5-FC					
6-FC					
7-FC					
8-FC		Paint chips ↓			Lead per Lead/Ernie Sweet 3/1/02
9-FC					
10-FC					

*For passive monitors please list time exposed in minutes.

Comments (Please list any known interferences present in sampling area):
11-FC

Chain of Custody	Print Name	Signature	Date/Time
Relinquished by:	<u>Ernie Sweet</u>	<u>Ernie Sweet</u>	<u>2/28/02 5pm</u>
Received by LAB:	<u>Bruce Baxter</u>	<u>Bruce Baxter</u>	<u>2/28/02 6pm</u>

Samples received after 3pm will be considered as next day's business.

LAB ORIGINAL

BCLP02766



Galsoni
Laboratories
6601 Kirkville Road
P.O. Box 369
E. Syracuse, NY 13057
Tel: (315) 437-7252 888-577-Labs (5227)
Fax: (315) 437-0571

Request For Industrial Hygiene Analysis

Company Name: Edm

Site Name: Luna Creek

Sampled By: *Erm*

Project #: 58910,00001

Send Report to:

Invoice to:

☐ Purchase order number

☐ Credit Card (type)

☒ Verbal Authorization

Card #

Exp Date

☒ Standard Turn-Around Time

OR

☐ Rush: Date and Time Requested:

am
pm

☐ Phone Results to:

Phone #

ext.

☒ Fax Results to: 315-445-2543

Fax #

☐ **Email Results to:**[illegible]

*For passive monitors please list time exposed in minutes.

Comments (Please list any known interferences present in sampling area):

Chain of Custody

Print Name

Signature

Date/Time

Relinquished by:

Received by LAB.

TOTAL P.09
BCLP02767